


Fig. 1


109750-10955860

Fig. 3



20250103101

Fig. 4






Fig. 5

FIG. 5




Fig. 6

208547US2-4955860

Fig. 7




Fig.8

Parts Requirement Information

Line No.	Model Name	Part No.	Part Name	Date	Time	Quantity
L1	PRT1	PTS1	***	***	10:00	20
L3	PRT1	PTS3	***	***	9:00	10
L5	PRT2	PTS5	***	***	8:00	5
:	:	:	:	:	:	:

Delivery Status Information

Part No.	Part	Quantity	Destination	Date	Time
PTS1	***	20	L3	***	10:00
PTS3	***	10	L1	***	9:00
:	:	:	:	:	:

02855664-051601

Fig. 9




Fig.10

Shortage of Parts							
Model Name	Part No.	Part Name	Supplier	Requirement Source	Date of Requirement	Time of Requirement	Delivery Schedule
PRT1	AAA	***	***	***	*****	****	Ordered
PRT2	BBB	***	***	***	*****	****	Wait for Delivery

Fig. 11




Figure 1

Shipment Status

Complaint Details							
Gate	Model Name	Quantity	Destination	Preparation	Packing	Document-ation	Formalities for Shipment
	1 PRT1	**	***				
	4 PRT3	**	***				
	2 PRT2	**	***				
	3 PRT1	**	***				
	6 PRT1	**	***				

Fig. 13




Fig.14

Order of Parts

Model Name	Part No.	Part name	Supplier	Date of Requirement	Time of Requirement	Delivery Schedule
PRT1	AAA	***	***	*****	***:**	—
PRT2	BBB	***	***	*****	***:**	***:**
:	:	:	:	:	:	:

Delivery Status

Model Name	Part No.	Part Name	Supplier	Delivery Schedule	Date of Delivery	Time of Delivery
PRT1	AAA	***	***	***:**	*****	***:**
PRT2	BBB	***	***	***:**	*****	***:**
:	:	:	:	:	:	:

2025.04.15.15.33




Fig. 15

FILE NO. 12555860